



PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	LL9624886	Spindle
2	1	LL9624885	Hex Nut
3	2	LL9624888	Valve Adjusting Washer
4	2	LL9644209	Shut off Valve (Hard)
5	1	LL9624312	Thrust Bearing
6	1	LL9624889	Spindle Bearing
7	1	LL9618298	Hanger Bearing
8	1	LL9624313	Compression Spring
9	1	LL9622918	Lock Nut
10	1	LL9643602	Inner Tube Cap
11	1	LL9662374	Stainless Steel Ball
12	1	LL9637382	Check Valve Body
13	1	LL9617447	Grease Zerk

THIS DRAWING CONTAINS PROPRIETARY INFORMATION AND SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR ANY MANUFACTURING WITHOUT PERMISSION FROM NORTHWEST MACHINE WORKS . ALL DRAWINGS MUST BE RETURNED UPON REQUEST.

PROGRAM NO	REV	GENERAL SPECIFICATIONS UNLESS OTHERWISE SPECIFIED RADIUS ALL CORNERS .0313 ANGLES = +/-1° DEBURR ALL SHARP CORNERS				NO:	REVISIONS:	DATE:	DRAWN BY:	ISSUED
										Paul C
			NWL LOCK N LOAD® BEARING ASSEMBLY							
			MATERIAL:							
		X	XX	XXX	2318 GRAND PARK DR. GRAND JUNCTION, CO 81505 970-242-1356				DWG NO.	
		.031	.01	.005						LL9624000
		250	125	63						