



| PARTS LIST | | | |
|------------|-----|-------------|------------------------|
| ITEM | QTY | PART NUMBER | DESCRIPTION |
| 1 | 1 | LL9825231 | Spindle |
| 2 | 1 | LL9844574 | Hex Nut |
| 3 | 2 | LL9825233 | Valve Adjusting Washer |
| 4 | 2 | LL9843513 | Shut Off Valve (Hard) |
| 5 | 2 | LL9824528 | Thrust Bearing |
| 6 | 1 | LL9825234 | Spindle Bearing |
| 7 | 1 | LL9824312 | Hanger Bearing |
| 8 | 1 | LL9824529 | Compression Spring |
| 9 | 1 | LL98103465 | Lock Nut |
| 10 | 1 | LL9840401 | Inner Tube Cap |
| 11 | 1 | LL9862374 | Stainless Steel Ball |
| 12 | 1 | LL9837382 | Check Valve Body |
| 13 | 1 | LL9817447 | Grease Zerk |

THIS DRAWING CONTAINS PROPRIETARY INFORMATION AND SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR ANY MANUFACTURING WITHOUT PERMISSION FROM NORTHWEST MACHINE WORKS . ALL DRAWINGS MUST BE RETURNED UPON REQUEST.

| | | | | | | | | | | |
|------------|-----|--|-----|-----------------------------------|---|-----|------------|-------|-----------|--------|
| PROGRAM NO | REV | GENERAL SPECIFICATIONS UNLESS OTHERWISE SPECIFIED RADIUS ALL CORNERS .0313 ANGLES = +/-1° DEBURR ALL SHARP CORNERS | | | | NO: | REVISIONS: | DATE: | DRAWN BY: | ISSUED |
| | | | | | | | | | | Paul C |
| | | | | CHECKED BY: | | | | | | |
| | | | | HWL LOCK N LOAD® BEARING ASSEMBLY | | | | | | |
| | | X | XX | XXX | 2318 GRAND PARK DR. GRAND JUNCTION, CO 81505 970-242-1356 | | | | MATERIAL: | |
| | | .031 | .01 | .005 | | | | | DWG NO. | |
| | | 250 | 125 | 63 | | | | | LL9824000 | |