



PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	LL9724331	SPINDLE
2	1	LL9744601	HEX NUT
3	2	LL9744208	SHUT OFF VALVE (HARD)
4	2	LL9724335	VALVE ADJUSTING WASHER
5	2	LL9724030	THRUST BEARING
6	1	LL9724336	SPINDLE BEARING
7	1	LL9724031	COMPRESSION SPRING
8	1	LL97103144	LOCK NUT
9	1	LL9740676	INNER TUBE CAP
10	1	LL9724943	STAINLESS STEEL BALL
11	1	LL9740656	CHECK VALVE BODY
12	1	LL9717447	GREASE ZERK

THIS DRAWING CONTAINS PROPRIETARY INFORMATION AND SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR ANY MANUFACTURING WITHOUT PERMISSION FROM NORTHWEST MACHINE WORKS . ALL DRAWINGS MUST BE RETURNED UPON REQUEST.

PROGRAM NO	REV	<b>GENERAL SPECIFICATIONS UNLESS OTHERWISE SPECIFIED</b> ALL RADIUS ALL CORNERS .0313 ANGLES= +/-1° FINISH= DEBURR ALL SHARP CORNERS			 2318 GRAND PARK DR. GRAND JUNCTION, CO 81520 970-242-1356	NO:	REVISIONS:	DATE:	DRAWN BY: Paul C	ISSUED 11/16/2012	
		X	XX	XXX						CHECKED BY:	
		.031	.01	.005							BWL LOCK N LOAD® BEARING ASSEMBLY
		250	125	63						MATERIAL:	
									DWG NO. LL9724000		